




Power Electronics

The Synchronous Machine Modelling




Lorentz and Reluctance forces


PM
PM rotor




1-phase stator
PM rotor




2-phase stator
PM rotor




3-phase stator
PM rotor




3-phase stator
Reluctance & PM rotor




PM stator
Reluctance rotor




1-phase stator
Reluctance rotor




2-phase stator
Reluctance & PM rotor






3-phase stator
Reluctance & PM rotor



3-phase stator
Reluctance & PM rotor



of poles = p



$$\omega_{el} = \frac{p}{2} \cdot \omega_{mech}$$

$$T_{mech} = \frac{p}{2} \cdot T_{el}$$


$$\text{Mechanical Power} = \omega_{mech} \cdot T_{mech} = \frac{p}{2} \cdot \omega_{el} \cdot \frac{2}{p} \cdot T_{el} = \omega_{el} \cdot T_{el}$$


Inner or Outer Rotor, Radial or Axial flux

Inner rotor
Radial flux


Axial flux

Outer rotor
Radial flux





Distributed or Concentrated winding




- ***Axially shorter end winding***
- ***Cheaper assembly***
- ***Lower torque quality***



- ***Longer end winding***
- ***More expensive assembly***
- ***Higher torque quality***


Form Factor

- For the same torque, a machine can be either short and wide, or long and slender ...
- Assume 25 000 [N/m²], and a desired torque of 1000 Nm, AND that the stator outer radius is 0.15 – 0.5 meter.
 - How long will the machine be to fulfill the torque requirement?
- The long and slender machine will accelerate faster
 - $Torque \sim radius^2 * length$
 - $Inertia \sim radius^4 * length$
- $Acceleration = Torque/Inertia \sim 1/radius^2$







Permanent Magnet Synchronous Machines






- Same as the generic machine.
- Voltage and frequency proportional to speed.
- Current proportional to torque.
- High continuous torque density:
 - *1...10 Nm/kg*
 - *Compare to ICE 1...2 Nm/kg*
- High efficiency:
 - *Up to 97%*
- Higher efficiency, higher torque density and more expensive than other machines:
 - *Due to the permanent magnets.*



PMSM - Inner and outer rotor





Electrically magnetized




Can be made in 2 ways:

- Conductive
- Inductive

Different Magnet arrangements





IPM
(Interior Permanent Magnet)



SPM
(Surface Mounted Permanent Magnet)

Example from Toshiba

- "Large Torque and High Efficiency Permanent Magnet Reluctance Motor for A Hybrid Truck" - Masanori Arata et. Al, EVS-22




(a) An example of cross section of the PRM

Whiteboard ...





Current control of a 3- phase load

3 – phase converters



- In AC motor drives
- In grid connected converters

The generic 3-phase load



$$\sqrt{\frac{2}{3}} \left(u_a = R \cdot i_a + L \cdot \frac{di_a}{dt} + e_a \right)$$

$$+ \sqrt{\frac{2}{3}} \cdot e^{j \frac{2\pi}{3}} \cdot \left(u_b = R \cdot i_b + L \cdot \frac{di_b}{dt} + e_b \right)$$


$$+ \sqrt{\frac{2}{3}} \cdot e^{j \frac{4\pi}{3}} \cdot \left(u_c = R \cdot i_c + L \cdot \frac{di_c}{dt} + e_c \right)$$

$$\vec{u} = R \cdot \vec{i} + L \cdot \frac{d\vec{i}}{dt} + \vec{e}$$


Power-invariants

$$p(t) = u_a \cdot i_a + u_b \cdot i_b + u_c \cdot i_c = u_\alpha \cdot i_\alpha + u_\beta \cdot i_\beta$$

Symmetric emf



$$\begin{cases} e_a = \hat{e} \cdot \cos(\omega \cdot t) \\ e_b = \hat{e} \cdot \cos\left(\omega \cdot t - \frac{2\pi}{3}\right) \\ e_c = \hat{e} \cdot \cos\left(\omega \cdot t - \frac{4\pi}{3}\right) \end{cases}$$



Example, grid voltage vector

$$\begin{aligned}\bar{e} &= \sqrt{\frac{2}{3}} \cdot \left(e_a + e_b \cdot e^{j\frac{2\pi}{3}} + e_c \cdot e^{j\frac{4\pi}{3}} \right) = \\ &= \sqrt{\frac{2}{3}} \cdot \hat{e} \cdot \left(\cos(\omega \cdot t) + \cos\left(\omega \cdot t - \frac{2\pi}{3}\right) \cdot \left(-\frac{1}{2} + j\frac{\sqrt{3}}{2}\right) + \cos\left(\omega \cdot t - \frac{4\pi}{3}\right) \cdot \left(-\frac{1}{2} - j\frac{\sqrt{3}}{2}\right) \right) = \\ &= \sqrt{\frac{2}{3}} \cdot \hat{e} \cdot \left(\cos(\omega \cdot t) + \left(\cos(\omega \cdot t) \cdot \cos\left(\frac{2\pi}{3}\right) + \sin(\omega \cdot t) \cdot \sin\left(\frac{2\pi}{3}\right) \right) \cdot \left(-\frac{1}{2} + j\frac{\sqrt{3}}{2}\right) \right. \\ &\quad \left. + \left(\cos(\omega \cdot t) \cdot \cos\left(\frac{4\pi}{3}\right) + \sin(\omega \cdot t) \cdot \sin\left(\frac{4\pi}{3}\right) \right) \cdot \left(-\frac{1}{2} - j\frac{\sqrt{3}}{2}\right) \right) = \\ &= \sqrt{\frac{2}{3}} \cdot \hat{e} \cdot \left(\cos(\omega \cdot t) \cdot \left(1 + \frac{1}{4} + \frac{1}{4}\right) + j \cdot \sin(\omega \cdot t) \cdot \left(\frac{3}{4} + \frac{3}{4}\right) \right) = \\ &= \sqrt{\frac{3}{2}} \cdot \hat{e} \cdot (\cos(\omega \cdot t) + j \cdot \sin(\omega \cdot t)) = \boxed{E \cdot e^{j\omega t}}\end{aligned}$$

Voltage equation in the (α, β) and the (x, y) -frame

- Define the rotating reference frame (d, q) by \vec{E} and its Integral


$$\vec{\psi} = \int_0^t \vec{e} \cdot dt = \int_0^t E \cdot e^{j\omega t} dt = \frac{\vec{e}}{j \cdot \omega} = \frac{E}{\omega} e^{j\left(\omega t - \frac{\pi}{2}\right)}$$

- Express the stator equation in either the stator reference frame (α, β)

$$\vec{u} = R \cdot \vec{i} + L \cdot \frac{d\vec{i}}{dt} + \vec{e}$$

- Or in the rotor reference frame (d, q)

$$\vec{u} = R \cdot \vec{i} + L \cdot \frac{d\vec{i}}{dt} + j \cdot \omega \cdot L \cdot \vec{i} + \vec{e}$$



Derive the Control in the rotor reference frame

Assume sampled control @ [..., k, k+1, k+2, ...]Ts

Calculate voltage average over one sample period

$$\frac{\int_{k \cdot T_s}^{(k+1)T_s} \vec{u} \cdot dt}{T_s} = \frac{R \cdot \int_{k \cdot T_s}^{(k+1)T_s} \vec{i} \cdot dt + L \cdot \int_{k \cdot T_s}^{(k+1)T_s} \frac{d\vec{i}}{dt} \cdot dt + j \cdot \omega \cdot L \int_{k \cdot T_s}^{(k+1)T_s} \vec{i} \cdot dt + \int_{k \cdot T_s}^{(k+1)T_s} \vec{e} \cdot dt}{T_s} =$$
$$= \vec{u}(k, k+1) = (R + j \cdot \omega \cdot L) \cdot \vec{i}(k, k+1) + L \cdot \frac{\vec{i}(k+1) - \vec{i}(k)}{T_s} + \vec{e}(k, k+1)$$

Make some assumptions ...

Assume:

$$\vec{u}(k, k+1) = \vec{u}^*(k) \quad (a)$$

$$\vec{i}(k+1) = \vec{i}^*(k) \quad (b)$$

$$\vec{i}(k, k+1) = \frac{\vec{i}^*(k) + \vec{i}(k)}{2} \quad (c)$$

$$\vec{e}(k, k+1) = \vec{e}(k) \quad (d)$$

$$\vec{i}(k) = \sum_{n=0}^{n=k-1} (\vec{i}^*(n) - \vec{i}(n)) \quad (e)$$

Gives:

$$\vec{u}^*(k) = (R + j \cdot \omega \cdot L) \cdot \frac{\vec{i}^*(k) + \vec{i}(k)}{2} + L \cdot \frac{\vec{i}^*(k) - \vec{i}(k)}{T_s} + \vec{e}(k) =$$

$$= R \cdot \frac{\vec{i}^*(k) - \vec{i}(k)}{2} + R \cdot \vec{i}(k) + L \cdot \frac{\vec{i}^*(k) - \vec{i}(k)}{T_s} + j \cdot \omega \cdot L \cdot \frac{\vec{i}^*(k) + \vec{i}(k)}{2} + \vec{e}(k) \approx$$

$$\approx \left(\frac{L}{T_s} + \frac{R}{2} \right) (\vec{i}^*(k) - \vec{i}(k)) + R \cdot \sum_{n=0}^{n=k-1} (\vec{i}^*(n) - \vec{i}(n)) + j \cdot \omega \cdot L \cdot \vec{i}(k) + \vec{e}(k) =$$

$$= \left(\frac{L}{T_s} + \frac{R}{2} \right) \cdot \left(\underbrace{(\vec{i}^*(k) - \vec{i}(k))}_{\text{Proportional}} + \underbrace{\frac{T_s}{\left(\frac{L}{R} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} (\vec{i}^*(n) - \vec{i}(n))}_{\text{Integral}} \right) + \underbrace{j \cdot \omega \cdot L \cdot \vec{i}(k) + \vec{e}(k)}_{\text{Feed forward}}$$

Current Controllers split on d - and q -


- **Components**

$$u_d^*(k) = \left(\frac{L}{T_s} + \frac{R}{2} \right) \cdot \left(i_d^*(k) - i_d(k) \right) + \frac{T_s}{\left(\frac{L}{R} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left(i_d^*(n) - i_d(n) \right) - \omega \cdot L \cdot i_q(k)$$

$$u_q^*(k) = \left(\frac{L}{T_s} + \frac{R}{2} \right) \cdot \left(i_q^*(k) - i_q(k) \right) + \frac{T_s}{\left(\frac{L}{R} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left(i_q^*(n) - i_q(n) \right) + \omega \cdot L \cdot i_d(k) + e_q(k)$$


- **Some evaluation of values ...**

- >> $L=1e-3$;
- >> $R=0.05$;
- >> $T_s=100e-6$;
- >> $[L/T_s \ R/2] = [10.0000 \ 0.0250]$
- >> $[L/R \ T_s/2] = [0.0200 \ 0.0001]$



- The inductance defines the gain
- The electric time constant defines the Integral gain

Control in a rotating reference frame





Modelling and control of a PMSM

3-phase winding currents as vectors


- Assign each winding a direction
- Scale each equations contribution with a unity vector in each direction
- Add the equations, vectorially ...

$$\begin{aligned}
 & \sqrt{\frac{2}{3}} \cdot \left(u_a = R_s \cdot i_a + \frac{d\psi_a}{dt} = R_s \cdot i_a + \frac{d}{dt} (\psi_{\delta a} + L_{s\lambda} \cdot i_a) \right) \\
 + & e^{j\frac{2\pi}{3}} \cdot \sqrt{\frac{2}{3}} \cdot \left(u_b = R_s \cdot i_b + \frac{d\psi_b}{dt} = R_s \cdot i_b + \frac{d}{dt} (\psi_{\delta b} + L_{s\lambda} \cdot i_b) \right) \\
 + & e^{j\frac{4\pi}{3}} \cdot \sqrt{\frac{2}{3}} \cdot \left(u_c = R_s \cdot i_c + \frac{d\psi_c}{dt} = R_s \cdot i_c + \frac{d}{dt} (\psi_{\delta c} + L_{s\lambda} \cdot i_c) \right)
 \end{aligned}$$

$$\vec{u}_s^{\alpha\beta} = R_s \cdot \vec{i}_s^{\alpha\beta} + \frac{d\vec{\psi}_s^{\alpha\beta}}{dt} = R_s \cdot \vec{i}_s^{\alpha\beta} + \frac{d}{dt} (\vec{\psi}_{\delta}^{\alpha\beta} + L_{s\lambda} \cdot \vec{i}_s^{\alpha\beta})$$

PM-flux linkage + the stator currents own contribution to the air gap flux linkage

The stator currents own leakage flux linkage



Introduce the rotor reference frame (x,y) ...

- Express the stator equation in the rotor reference frame

$$\vec{u}_s^{\alpha\beta} = R_s \cdot \vec{i}_s^{\alpha\beta} + \frac{d}{dt} (\vec{\psi}_\delta^{\alpha\beta} + L_{s\lambda} \cdot \vec{i}_s^{\alpha\beta})$$

$$\{\vec{s}_s^{\alpha\beta} = \vec{s}_s^{xy} \cdot e^{j\theta_r}\}$$


$$\begin{aligned} \vec{u}_s^{xy} \cdot e^{j\theta_r} &= R_s \cdot \vec{i}_s^{xy} \cdot e^{j\theta_r} + \frac{d}{dt} (\vec{\psi}_\delta^{xy} \cdot e^{j\theta_r} + L_{s\lambda} \cdot \vec{i}_s^{xy} \cdot e^{j\theta_r}) \\ &= R_s \cdot \vec{i}_s^{xy} \cdot e^{j\theta_r} + \frac{d}{dt} (\vec{\psi}_\delta^{xy} + L_{s\lambda} \cdot \vec{i}_s^{xy}) \cdot e^{j\theta_r} + j \cdot \frac{d\theta_r}{dt} \cdot (\vec{\psi}_\delta^{xy} + L_{s\lambda} \cdot \vec{i}_s^{xy}) \cdot e^{j\theta_r} \end{aligned}$$

$$\vec{u}_s^{xy} = R_s \cdot \vec{i}_s^{xy} + \frac{d}{dt} (\vec{\psi}_\delta^{xy} + L_{s\lambda} \cdot \vec{i}_s^{xy}) + j \cdot \omega_r \cdot (\vec{\psi}_\delta^{xy} + L_{s\lambda} \cdot \vec{i}_s^{xy})$$

- Split up the complex equation in real- and imaginary parts:

$$\begin{aligned} u_{sx} &= R_s \cdot i_{sx} + \frac{d}{dt} (\psi_m + L_{mx} \cdot i_{sx} + L_{s\lambda} \cdot i_{sx}) - \omega_r \cdot (L_{my} \cdot i_{sy} + L_{s\lambda} \cdot i_{sy}) = \\ &= R_s \cdot i_{sx} + \frac{d}{dt} (\psi_m + L_{sx} \cdot i_{sx}) - \omega_r \cdot L_{sy} \cdot i_{sy} \end{aligned}$$

$$\begin{aligned} u_{sy} &= R_s \cdot i_{sy} + \frac{d}{dt} (L_{my} \cdot i_{sy} + L_{s\lambda} \cdot i_{sy}) + \omega_r \cdot (\psi_m + L_{mx} \cdot i_{sx} + L_{s\lambda} \cdot i_{sx}) = \\ &= R_s \cdot i_{sy} + L_{sy} \cdot \frac{di_{sy}}{dt} + \omega_r \cdot (\psi_m + L_{sx} \cdot i_{sx}) \end{aligned}$$



The 3-phase winding is electronically commutated

- The i_{sx} and i_{sy} currents cannot be supplied directly!
- Instead, they have to be supplied as 3 phase currents
- The translation is made in two steps:
- First, from xy to $\alpha\beta$:

$$\vec{i}_s^{xy} = i_{sx} + ji_{sy} = i_s e^{j\gamma}$$

$$\vec{i}_s^{\alpha\beta} = \vec{i}_s^{xy} e^{j\theta_r} = i_s e^{j(\gamma+\theta_r)} = i_{s\alpha} + ji_{s\beta}$$


$$i_{s\alpha} + ji_{s\beta} = i_s \cos(\omega_r t + \gamma) + ji_s \sin(\omega_r t + \gamma)$$

- Then, from $\alpha\beta$ to abc :


$$i_a = \sqrt{\frac{2}{3}} i_{s\alpha}$$

$$i_b = \sqrt{\frac{2}{3}} \left(-\frac{1}{2} i_{s\alpha} + \frac{\sqrt{3}}{2} i_{s\beta} \right)$$

$$i_c = \sqrt{\frac{2}{3}} \left(-\frac{1}{2} i_{s\alpha} - \frac{\sqrt{3}}{2} i_{s\beta} \right)$$



The PMSM – like the ideal 3-phase load



$$\begin{aligned} & \sqrt{\frac{2}{3}} \left(u_{sa} = R_s \cdot i_{sa} + \frac{d\psi_{sa}}{dt} \right) \\ & \sqrt{\frac{2}{3}} \cdot e^{j\frac{2\pi}{3}} \cdot \left(u_{sb} = R_s \cdot i_{sb} + \frac{d\psi_{sb}}{dt} \right) \\ & + \sqrt{\frac{2}{3}} \cdot e^{j\frac{4\pi}{3}} \cdot \left(u_{sc} = R_s \cdot i_{sc} + \frac{d\psi_{sc}}{dt} \right) \\ \hline \vec{u}_s &= R_s \cdot \vec{i}_s + \frac{d\vec{\psi}_s}{dt} \end{aligned}$$


Mathematical Model – Voltage and Current

- The PMSM has:
 - a 3-phase winding, with resistance and inductance
 - A back emf
- It can be described with the same equation as the ideal 3-phase load – in the ROTOR reference frame (x,y)

$$\vec{u}_s = R_s \cdot \vec{i} + L_s \cdot \frac{d\vec{i}}{dt} + j \cdot \omega \cdot L_s \cdot \vec{i} + \vec{e}_s$$

$$\vec{e}_a = j \cdot \omega_{el} \cdot \psi_m$$

$$\vec{u}_s^{xy} = R_s \cdot \vec{i}_s^{xy} + L_s \cdot \frac{d\vec{i}_s^{xy}}{dt} + j\omega_r \cdot (\psi_m^{xy} + L_s \cdot \vec{i}_s^{xy})$$




3-phase sampled vector control : 4

Components:


$$u_{sx}^*(k) = \left(\frac{L_s}{T_s} + \frac{R}{2} \right) \cdot \left(i_{sx}^*(k) - i_{sx}(k) \right) + \frac{T_s}{\left(\frac{L_s}{R_s} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left(i_{sx}^*(n) - i_{sx}(n) \right) - \omega_{el} \cdot L \cdot i_{sy}(k)$$
$$u_{sy}^*(k) = \left(\frac{L_s}{T_s} + \frac{R}{2} \right) \cdot \left(i_{sy}^*(k) - i_{sy}(k) \right) + \frac{T_s}{\left(\frac{L_s}{R_s} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left(i_{sy}^*(n) - i_{sy}(n) \right) + \omega_{el} \cdot L \cdot i_{sx}(k) + e_{sy}(k)$$

Control in a rotating reference frame

Torque ref
Speed
DC link voltage



Some Simulink





End of modelling lecture

© Mats Alaküla

Power Electronics / Speed & Position Control