




Torque Control of Induction Machines as compared to PMSM

Power Electronics / Induction Machine



The Induction Machine



Three Phase Stator

No Magnets in the Rotor


Rotor as Short Circuited "Cage"

The rotor current must be induced

Three Phase Stator

Three phase power electronics

A look under the hood



Power Electronics / Induction Machine




Advantages

- **Self starting when connected to the power grid**
- **Robust and reliable**
- **Cheap**
- **Low maintenance**
- **Standardized**

IM - dynamics


Start here ...

Move the stator current one step
– what happens in the rotor?




Consequences

- The rotor current is
 - Proportional to
**The stator flux and
The speed difference (both
tangentially and radially)**
 - Inversely proportional to the **rotor
resistance**
 - **90 degrees lag versus the flux**











Torque properties

$$T = \psi_s \cdot i_r = (\omega - \omega_r) \cdot \frac{\hat{\psi}_s^2}{R_r}$$





Connection

Motor	3~	50 Hz	IEC 34-1
			No.
2.2 kW		2820 r/min	
		cos φ 0,89	
	 380 V 4.7 A		 220 V 8.15 A
19.0 kg		IP 54	Cl. F




Single phase operation

- Steinmetz connection
- Shaded pole motor




Summering AM

- **Rotation**
 - *With AC winding in the Stator*
- **Voltage**
 - *Proportional to frequency*
- **Speed**
 - *Also proportional to frequency, BUT WITH A SLIP @ Non-Zero Torque*
- **Torque**
 - *Proportional to y-axis current*




Mechanical design of IM

- Stator same as PMSM
- Rotor:




Cast aluminum






Wound copper /Slip ring

Slip ring rotor



The rotor can be:

- 1 *Short circuited*
- 2 *Given an external rotor resistance*
- 3 *Fed by power electronics*



Power Electronics / Induction Machine


Mathematical model

- Stator


- Rotor

$$\vec{u}_s = R_s \cdot \vec{i}_s + \frac{d\vec{\psi}_s}{dt}$$

$$\vec{u}_r = R_s \cdot \vec{i}_r + \frac{d\vec{\psi}_r}{dt}$$



How does it work?




Imagine the following sequence :

- 1 A magnetizing stator current is stationary vs. the rotor.
- 2 The current is instantly moved and increased.
- 3 The rotor conserves the (rotor-)flux and thus the stator flux



Torque



Rotor flux orientation

$$T = \vec{\psi}_s \times \vec{i}_s = \vec{\psi}_r \times \vec{i}_r = -\frac{L_m}{L_s} \cdot \vec{\psi}_s \times \vec{i}_r = \frac{L_m}{L_s} \cdot \vec{\psi}_r \times \vec{i}_s = \vec{\psi}_\delta \times \vec{i}_s$$

Stator flux orientation



Vector control of Induction machines

- Control usually made in EITHER:
 - The **stator** flux oriented reference frame
 - OR
 - The **rotor** flux oriented reference frame
- Control, independent of frame, is usually the easiest
- Determining the reference frame is more difficult.

Rotor flux estimation 1


- Rewriting the 2 (rotor and stator) vector equations -> 4 scalar equations
- That can be expressed like this (rotor equations first, stator equations last)

$$\frac{d\psi_{rd}}{dt} = \frac{L_m}{\tau_r} \cdot i_{sd} - \frac{1}{\tau_r} \cdot \psi_{rd}$$


$$\frac{d\theta_{sl}}{dt} = \frac{L_m \cdot i_{sq}}{\tau_r \cdot \psi_{rd}}$$

$$\frac{di_{sd}}{dt} = \left[u_{sd} - R_s \cdot i_{sd} - \frac{L_m}{L_r} \cdot \frac{d\psi_{rd}}{dt} + \omega_s \cdot \sigma \cdot L_s \cdot i_{sq} \right] \cdot \frac{1}{\sigma \cdot L_s}$$

$$\frac{di_{sq}}{dt} = \left[u_{sq} - R_s \cdot i_{sq} - \omega_s \cdot \left(\sigma \cdot L_s \cdot i_{sd} + \frac{L_m}{L_r} \cdot \psi_{rd} \right) \right] \cdot \frac{1}{\sigma \cdot L_s}$$



Rotor flux estimation 2



Full Flux Observer 1 (to estimate both rotor and stator flux in the same time)

$$\vec{u}_s = R_s \cdot \vec{i}_s + \frac{d\vec{\psi}_s}{dt}$$

$$0 = R_r \cdot \vec{i}_r + \frac{d\vec{\psi}_r}{dt} - j \cdot \omega_r \cdot \vec{\psi}_r$$

⇓

$$\begin{bmatrix} \vec{u}_s \\ 0 \end{bmatrix} = \begin{bmatrix} R_s & 0 \\ 0 & R_r \end{bmatrix} \cdot \begin{bmatrix} \vec{i}_s \\ \vec{i}_r \end{bmatrix} + \frac{d}{dt} \begin{bmatrix} \vec{\psi}_s \\ \vec{\psi}_r \end{bmatrix} + \begin{bmatrix} 0 & 0 \\ 0 & -j \cdot \omega_r \end{bmatrix} \cdot \begin{bmatrix} \vec{\psi}_s \\ \vec{\psi}_r \end{bmatrix}$$

$u = R \cdot i + \frac{d\psi}{dt} + \Omega \cdot \psi$

Full Flux Observer 2

$$\frac{d\psi}{dt} = u - R \cdot i - \Omega \cdot \psi = \begin{cases} \psi = L \cdot i \\ i = L^{-1} \cdot \psi \end{cases} = -\left(R \cdot L^{-1} + \Omega\right) \cdot \psi + u$$

$$\begin{aligned} \frac{d\hat{\psi}}{dt} &= -\left(R \cdot L^{-1} + \Omega\right) \cdot \hat{\psi} + u + R \cdot k \cdot (i_s - C \cdot \hat{\psi}) = \\ &= -\left(R \cdot L^{-1} + \Omega - R \cdot k \cdot C\right) \cdot \hat{\psi} + u + R \cdot k \cdot i_s = \\ &= A_{\text{obs}} \cdot \hat{\psi} + B \cdot u + R \cdot k \cdot i_s \end{aligned}$$

where

$$R = \begin{bmatrix} R_s & 0 \\ 0 & R_r \end{bmatrix}; L = \begin{bmatrix} L_s & L_m \\ L_m & L_r \end{bmatrix}; \psi = \begin{bmatrix} \vec{\psi}_s \\ \vec{\psi}_r \end{bmatrix}; B = \begin{bmatrix} 1 \\ 0 \end{bmatrix}$$

$$u = \begin{bmatrix} \vec{u}_s \\ 0 \end{bmatrix}; C = L^{-1}(1, :); \Omega = \begin{bmatrix} 0 & 0 \\ 0 & -j \cdot \omega_r \end{bmatrix}$$

Full Flux Observer 3

$$\hat{\psi}(k+1) = \mathbf{F}_{obs} \cdot \hat{\psi}(k) + \mathbf{G}_{obs} \cdot \bar{\mathbf{u}}(k, k+1) + \mathbf{K}_{obs} \cdot \bar{\mathbf{i}}_s(k, k+1)$$

$$\begin{aligned} \mathbf{F}_{obs} &= e^{\mathbf{A}_{obs} \cdot T_s} = e^{-(\mathbf{R} \cdot \mathbf{L}^{-1} + \boldsymbol{\Omega} + \mathbf{R} \cdot \mathbf{k} \cdot \mathbf{C}) \cdot T_s} \approx \\ &\approx e^{-\boldsymbol{\Omega} \cdot T_s / 2} \cdot e^{-(\mathbf{R} \cdot \mathbf{L}^{-1} + \mathbf{R} \cdot \mathbf{k} \cdot \mathbf{C}) \cdot T_s} \cdot e^{-\boldsymbol{\Omega} \cdot T_s / 2} = \end{aligned}$$

$$= \begin{bmatrix} 0 & 0 \\ 0 & e^{j \cdot \omega_r \cdot T_s / 2} \end{bmatrix} \cdot \mathbf{F}_{obs, \omega_r=0} \cdot \begin{bmatrix} 0 & 0 \\ 0 & e^{j \cdot \omega_r \cdot T_s / 2} \end{bmatrix}$$

$$\mathbf{F}_{obs} = \left[\mathbf{I} - \mathbf{A}_{obs} \cdot \frac{T_s}{2} \right]^{-1} \cdot \left[\mathbf{I} + \mathbf{A}_{obs} \cdot \frac{T_s}{2} \right] \approx \left[\mathbf{I} + \mathbf{A}_{obs} \cdot \frac{T_s}{2} \right]^2$$



Voltage measurement

- Estimation by software
 - *Error prone at low speeds*
- Analogue filtering and sampling
 - *slow*
- Direct integration
 - *Needs galvanic isolation*

Split equation solving

$$\begin{bmatrix} \frac{d\vec{\psi}_s}{dt} \\ \frac{d\vec{\psi}_r}{dt} \end{bmatrix} = \begin{bmatrix} A_{obs,11} & A_{obs,12} \\ A_{obs,21} & A_{obs,22} \end{bmatrix} \cdot \begin{bmatrix} \hat{\vec{\psi}}_s \\ \hat{\vec{\psi}}_r \end{bmatrix} + \begin{bmatrix} 1 \\ 0 \end{bmatrix} \cdot \vec{u}_s + \begin{bmatrix} R_s \cdot k_1 \cdot \vec{i}_s \\ R_r \cdot k_2 \cdot \vec{i}_s \end{bmatrix}$$

$$\begin{aligned} \frac{d\vec{\psi}_s}{dt} &= A_{obs,11} \cdot \hat{\vec{\psi}}_s + A_{obs,12} \cdot \hat{\vec{\psi}}_r + \vec{u}_s + R_s \cdot k_1 \cdot \vec{i}_s \\ &= A_{obs,11} \cdot \hat{\vec{\psi}}_s + A_{obs,12} \cdot \hat{\vec{\psi}}_r + R_s \cdot k_1 \cdot \vec{i}_s + \vec{u}_s \end{aligned}$$

Solved partly outside the microprocessor


$$\frac{d\vec{\psi}_r}{dt} = A_{obs,21} \cdot \hat{\vec{\psi}}_s + A_{obs,22} \cdot \hat{\vec{\psi}}_r + 0 + R_r \cdot k_2 \cdot \vec{i}_s$$

Solved entirely in the microprocessor

Direct integration implemented

Software / microprocessor

Real analogue world



$$\frac{d\vec{\psi}_s}{dt} = A_{obs,11} \cdot \hat{\psi}_s + A_{obs,12} \cdot \hat{\psi}_r + \vec{u}_s + R_s \cdot k_1 \cdot \vec{i}_s$$

$$= A_{obs,11} \cdot \hat{\psi}_s + A_{obs,12} \cdot \hat{\psi}_r + R_s \cdot k_1 \cdot \vec{i}_s + \vec{u}_s$$

Solved partly outside the microprocessor

Power Electronics / Induction Machine



Stator Flux Oriented Vector Control of Torque and Flux

3 advantages:

- In a synchronously rotating reference frame, there are no stationary errors since all reference values are constant in stationarity
- The stator flux vector can in most cases be observed with high accuracy and low parameter sensitivity
- Direct flux control can be applied

Equations, but only the stator equations this time

- 2 vector equation, i.e. 4 scalar equations, rewritten gives :

$$\frac{d\psi_{sd}}{dt} = \frac{L_s}{\tau_r} \cdot i_{sd} - \frac{1}{\tau_r} \cdot \psi_{sd} + \left[\sigma \cdot L_s \cdot \frac{di_{sd}}{dt} - \omega_{sl} \cdot \sigma \cdot L_s \cdot i_{sq} \right] = u_{sd} - R_s \cdot i_{sd}$$

$$\frac{d\theta_{sl}}{dt} = \frac{L_s \cdot i_{sq} + \sigma \cdot L_s \cdot \tau_r \cdot \frac{di_{sq}}{dt}}{\tau_r \cdot \psi_{sd} - \sigma \cdot L_s \cdot \tau_r \cdot i_{sd}} = \frac{u_{sq} - R_s \cdot i_{sq}}{\psi_{sd}} - \omega_r$$

Direct Flux Vector Control

- The stator flux can in this particular case be controlled directly, without using a current control loop:
 - Use the *d*-axis stator voltage equation, and integrated over one sampling period.
 - Approximate the stator current to the stationary one.
 - This leads to a *p*-controller for the stator flux modulus.
- This is a possible, and somewhat beautiful control concept, but suffers from the lack of an inner current control loop to limit current in case of failure (e.g. short circuit in a winding)

$$u_{sd}(t) = R_s \cdot i_{sd}(t) + \frac{d\psi_{sd}(t)}{dt}$$

$$u_{sd}^*(k) = R_s \cdot \bar{i}_{sd}(k, k+1) + \frac{\psi_{sd}^*(k) - \psi_{sd}(k)}{T_s} =$$

$$= \left\{ \psi_{sd} = L_s \cdot i_{sd} \text{ in stationarity} \right\} =$$

$$\approx R_s \cdot \frac{\psi_{sd}(k)}{L_s} + \frac{\psi_{sd}^*(k) - \psi_{sd}(k)}{T_s}$$

Control of the Torque producing current component : 1

- The remaining equations can be combined into a version of the q -axis equation:
- This shows that the q -axis current controller is based on exactly the same type of equation as a current controller in the PMSM machine, just with different parameters:
 - *Stator+Rotor resistance*
 - *Stator leakage+Rotor leakages inductances*

$$u_{sq} = R_s \cdot i_{sq} + \omega_r \cdot \psi_{sd} + \left[\frac{L_s \cdot i_{sq} + \sigma \cdot L_s \cdot \tau_r \cdot \frac{di_{sq}}{dt}}{\tau_r \cdot \psi_{sd} - \sigma \cdot L_s \cdot \tau_r \cdot i_{sd}} \right] \cdot \psi_{sd}$$

$$u_{sq} = (R_s + R_r) \cdot i_{sq} + \sigma \cdot L_s \cdot \frac{di_{sq}}{dt} + \omega_r \cdot \psi_{sd} \approx$$


$$\approx (R_s + R_r) \cdot i_{sq} + (L_s \lambda + L_r \lambda) \cdot \frac{di_{sq}}{dt} + \omega_r \cdot \psi_{sd}$$

Control of the Torque producing current component : 2

- Use generic 1-phase load ...

$$u_{sq}^*(k) =$$
$$= \left(\frac{L_{s\lambda} + L_{r\lambda}}{T_s} + \frac{R_s + R_r}{2} \right) \cdot \left(i_{sq}^*(k) - \hat{i}_{sq}(k) \right) + \frac{T_s}{\left(\frac{L_{s\lambda} + L_{r\lambda}}{R_s + R_r} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left(i_{sq}^*(n) - \hat{i}_{sq}(n) \right) +$$
$$+ \omega_r \cdot \psi_{sd}(k)$$

Vector Control System




Power Electronics / Induction Machine



DTC


- **Compare to DCC.**
 - Replace i_{sd} with ψ_{sd}
 - Replace i_{sq} with T

DTC system



Power Electronics / Induction Machine



Simplified Stator Flux Model 1



$$\vec{u}_s = R \cdot \vec{i}_s + \frac{d\vec{\psi}_s}{dt} = R \cdot (\vec{i}_s - \vec{i}_{s0}) + R \cdot \vec{i}_{s0} + \frac{d\vec{\psi}_s}{dt}$$

$$\frac{d\vec{\psi}_s}{dt} = -R \cdot \vec{i}_{s0} + [\vec{u}_s - R \cdot (\vec{i}_s - \vec{i}_{s0})] = \begin{pmatrix} \text{no load running} \\ \vec{i}_s = \vec{i}_{s0} = \frac{\vec{\psi}_{s0}}{L_s} \end{pmatrix} = -R \cdot \frac{\vec{\psi}_{s0}}{L_s} + \vec{u}_s = -\frac{\vec{\psi}_{s0}}{\tau_s} + \vec{u}_s$$

Simplified Stator flux model 2





Simplified Stator Flux Model 3

$$\frac{d\psi_{sd}}{dt} = \frac{L_s}{\tau_r} \cdot i_{sd} - \frac{1}{\tau_r} \cdot \psi_{sd} + \left[\sigma \cdot L_s \cdot \frac{di_{sd}}{dt} - \omega_{sl} \cdot \sigma \cdot L_s \cdot i_{sq} \right] = u_{sd} - R_s \cdot i_{sd}$$


$$\frac{d\theta_{sl}}{dt} = \frac{L_s \cdot i_{sq} + \sigma \cdot L_s \cdot \tau_r \cdot \frac{di_{sq}}{dt}}{\tau_r \cdot \psi_{sd} - \sigma \cdot L_s \cdot \tau_r \cdot i_{sd}} = \frac{u_{sq} - R_s \cdot i_{sq}}{\psi_{sd}} - \omega_r$$

Simplified estimation error



Power Electronics / Induction Machine

Relation i_q/i_d in stator flux frame




Gopinath Style Flux Observer



$$\frac{d\Psi_r^r}{dt} = \frac{R_r L_m I_s^r}{L_r} - \frac{R_r}{L_r} \Psi_r^r$$

$$\frac{d\Psi_s^s}{dt} = V_s^s - R_s I_s^s$$

$$\frac{d\Psi_s^s}{dt} = V_s^s - R_s I_s^s$$



DB-DTFC



DB-DTFC

