


Thermal modelling and Position and Speed Control

Industrial Electrical Engineering and Automation
Lund University, Sweden



Thermal circuit



- Chip temperature ϑ_j
- Heat sink temperature ϑ_s
- Power losses P
- Thermal resistance R_{th}
- Thermal capacitance C_{th}

$$R_{th(j-s)} = \sum R_{th(layers)} \quad R_{th} = \frac{l}{\lambda A} \left[\frac{K}{W} \right]$$


$$C_{th(j-s)} = \sum C_{th(layers)} \quad C_{th} = mc \left[\frac{J}{K} \right]$$

$$R_{conv} = \frac{1}{A_{cool} h}$$

$$\vartheta_j = P_j (R_{th} + R_{conv}) + \vartheta_{amb}$$

Thermal circuit


- Heat flow
 - Heat sources: losses in diodes and transistors
 - Heat sink: natural or forced convection
 - Thermal resistance: components and thermal connections between them
- Thermal nodes
 - Junction
 - Case
 - Heat sink
 - Ambient
- Solutions
 - Steady state
 - Transient



$$\vartheta_{i,end} = (R_{th} \cdot P + \vartheta_{amb}) \cdot (1 - e^{-\frac{t}{\tau}}) + \vartheta_{i,start} \cdot e^{-\frac{t}{\tau}}$$

Simple converter loss model

- Switching waveforms, looking at turn-on, on-state and turn-off energy losses over switching sequence
- Considering temperature dependence
- Recalculate datasheet values to actual working point
- Pay attention if losses can be separated by components or they are provided as per integrated switch



Switching and conducting losses

Energy losses: $E_S(T_{sw}) = \int_{T_{sw}} p_S(\tau) d\tau = E_{S,on}(T_{sw}) + E_{S,cond}(T_{sw}) + E_{S,off}(T_{sw})$

$$E_{S,on}(T_{sw}) = \int_{t_{on}} p_S(\tau) d\tau = V_{DC} \cdot I_0 \cdot \frac{t_{on}}{2}$$

$$E_{S,cond}(T_{sw}) = \int_{t_{cond}} p_S(\tau) d\tau = V_{S(on)} \cdot I_0 \cdot t_{cond} \quad \text{Note} \quad V_{S(on)} = V_{S0} + R_S \cdot I_0$$

$$E_{S,off}(T_{sw}) = \int_{t_{off}} p_S(\tau) d\tau = V_{DC} \cdot I_0 \cdot \frac{t_{off}}{2}$$


Power losses: $P_S(T_{sw}) = \frac{E_S(T_{sw})}{T_{sw}} = P_{S,on}(T_{sw}) + P_{S,cond}(T_{sw}) + P_{S,off}(T_{sw})$

$$P_{S,on}(T_{sw}) = \frac{E_{S,on}(T_{sw})}{T_{sw}} = E_{S,on}(T_{sw}) \cdot f_{sw} = \frac{V_{DC} \cdot I_0 \cdot t_{on}}{2} \cdot f_{sw}$$

$$P_{S,cond}(T_{sw}) = \frac{E_{S,cond}(T_{sw})}{T_{sw}} = V_{S(on)} \cdot I_0 \cdot \frac{t_{cond}}{T_{sw}} = V_{S(on)} \cdot I_0 \cdot D_S$$

$$P_{S,off}(T_{sw}) = \frac{E_{S,off}(T_{sw})}{T_{sw}} = E_{S,off}(T_{sw}) \cdot f_{sw} = \frac{V_{DC} \cdot I_0 \cdot t_{off}}{2} \cdot f_{sw}$$

$$P_{S,sw}(T_{sw}) = P_{S,on}(T_{sw}) + P_{S,off}(T_{sw})$$



Turn on t_{on}
 On-state t_{cond}
 Turn off t_{off}

Reverse recovery losses

Nominal data

Case data

If specified, use:

$$E_{S,on}(T_{sw}) = \frac{E_{on,n}}{V_{DC,n} \cdot I_{0n}} \cdot V_{DC} \cdot I_0$$

$$E_{S,off}(T_{sw}) = \frac{E_{off,n}}{V_{DC,n} \cdot I_{0n}} \cdot V_{DC} \cdot I_0$$

For the freewheeling diode:

$$P_{D,cond}(T_{sw}) = V_{D(on)} \cdot I_0 \cdot D_D \quad V_{D(on)} = V_{D0} + R_D \cdot I_0$$

$$D_D \approx 1 - D_S$$

$$P_{D,rr} = V_{DC} \cdot Q_f \cdot f_{sw} \quad Q_f \approx \frac{1}{S+1} \cdot Q_{rr} \quad \text{where } S = \frac{t_{rr1}}{t_{rr2}}$$

If specified, use:

$$P_{D,off} = E_{D,off}(T_{sw}) \cdot f_{sw} \quad E_{D,off}(T_{sw}) = \frac{E_{off,n}}{V_{DC,n} \cdot I_{0n}} \cdot V_{DC} \cdot I_0$$

$$Q_f = \frac{Q_{f,n}}{I_{0n}} \cdot I_0$$




Figure 6.3: Diode turn-off.

Fall t_{ft}
 $di/dt < 0$ t_{rr1}
 $di/dt > 0$ t_{rr2}




Position and Speed Control


© Mats Alaküla

Power Electronics / Speed & Position Control

Generic Structure



Cascade Control




The system contains two integrations. This gives a hint about two properties of the system:

- 1 watch out for the stability margins;
- 2 integrators may help to eliminate remaining errors.


The mechanical system

$$\frac{d}{dt} (J \cdot \omega) = T_{el} - T_l$$



$$\frac{d}{dt} (J \cdot \omega) = J \cdot \frac{d\omega}{dt} + \omega \cdot \frac{dJ}{dt} = T_{el} - T_l$$


Position Control Without Speed Control



$$\frac{\theta(s)}{\theta^*(s)} = \frac{K_p}{J \cdot s^2 + K_p} \quad s = \pm \sqrt{-\frac{K_p}{J}}$$

Only oscillatory poles!

Position Control with Speed Control



$$\frac{\theta(s)}{\theta^*(s)} = \frac{K_p \cdot K_\omega}{J \cdot s^2 + K_\omega \cdot s + K_p \cdot K_\omega}$$

$$\text{poles} = -\frac{K_\omega}{2J} \pm \sqrt{\frac{K_\omega^2}{4J^2} - \frac{K_p \cdot K_\omega}{J}}$$


Limit for oscillatory poles:

$$\frac{K_\omega^2}{4J^2} - \frac{K_p \cdot K_\omega}{J} = 0$$

$$K_p = \frac{K_\omega}{4J}$$

Speed Control

Ideal torque source and speed sensing




Closed system:
$$\frac{\omega}{\omega^*} = \frac{K_w}{sJ + K_w} = \frac{1}{1 + s \frac{J}{K_w}}$$

Roots:
$$s = -\frac{K_w}{J}$$

i.e. any bandwidth possible, ... but then is no longer true ...


Example 1

- $T_{tc} = 0.001$;
- $J = 0.038$;
- Select $k_{\omega} = 100$;
- High gain + Unlimited and infinitely fast torque source




Conclusion 1

- Ideal conditions leads to a too fast speed controller. The torque source is not as fast in reality as it seems in the simulations.
- Try limiting the torque source in amplitude and dynamic response time.
 - *Simplest: LIMITED 1'st order time constant!*




Example 2

- Introduce a torque source, **LIMITED** in dynamic response time **AND** amplitude!




Conclusion 2

- Now the response time is much longer, and oscillatory when out of torque limitation ...
- What is a suitable gain?
 - *Derive the gain based on the assumption that the torque source reacts like a limited 1st order time constant*



Speed Control

Torque dynamics as first order low pass filter



Closed system:

$$\frac{\omega}{\omega^*} = \frac{\frac{k_w}{J \cdot T_{tc}}}{s^2 + s \cdot \frac{1}{T_{tc}} + \frac{k_w}{J \cdot T_{tc}}}$$

Roots:

$$-\frac{1}{2T_{tc}} \pm \sqrt{\frac{1}{4 \cdot T_{tc}^2} - \frac{k_w}{J \cdot T_{tc}}}$$

Non osc. roots ->

$$k_w = \frac{J}{4 \cdot T_{tc}^2}$$


Limited k_ω gives stationary error with P-control!!

Example 3

$$T_{tc} = 0.001$$


$$J = 0.034$$

$$\text{Select } k_{\omega} = J/4/T_{tc} = 9.5;$$



Conclusion 3

- Dynamics is realistic and the control system stable.
- What about stationary errors?





Toad torque can be:

- Constant
- Linear to speed
- Quadratic to speed.
 - *Try with constant 5 Nm*
- What happens?


Example 4

$$T_{tc} = 0.001;$$

$$J = 0.034;$$


Constant Load Torque 5 Nm

$$\text{Select } k_{\omega} = J/4/T_{tc} = 9.5$$



Conclusion 4

- With P-control and a "non-zero" load torque, there will be a stationary error.





Solution to stationary error, PI-control

Control error $e = y^*(t) - y(t)$

$$u(t) = K_p \cdot \left(e(t) + \frac{1}{\tau_i} \int e(t) dt \right)$$

$$u(s) = K_p \frac{1 + s\tau_i}{s\tau_i} e(s)$$

Digital PI controller


$$u(k) = K_p \cdot \left(y^*(k) - y(k) + \frac{T_s}{T_i} \sum_{n=0}^{n=k} (y^*(n) - y(n)) \right)$$

$$K_p \cdot \frac{T_s}{T_i} \sum_{n=0}^{n=k} (y^*(n) - y(n)) = u_{\text{int}}(k)$$

$$u(k) = K_p \cdot (y^*(k) - y(k)) + u_{\text{int}}(k)$$


Example 5

- How does the integrator react to the torque source limitation?
- Try with integration time $T_i = 0.1$ second?




Conclusion 5

- With the torque source limitation, the integrator integrates "in vain". The result is unstable!
- The problem is called "windup" of the integrator
- The solution is called "Anti Windup"




The torque source is limited

- Often speed dependent, e.g. “field weakening”



Analog anti windup (= history)



Digital Anti-Windup

$$u_{\text{int}}(k) = K_p \cdot \frac{T_s}{T_i} \sum_{n=0}^{n=k} (y^*(n) - y(n))$$

$$u(k) = K_p \cdot (y^*(k) - y(k)) + u_{\text{int}}(k)$$

if $u(k) > u_{\text{max}}$ or $u(k) < u_{\text{min}}$ then


$$u(k) = u_{\text{max}} \quad \text{or} \quad u(k) = u_{\text{min}}$$

$$u_{\text{int}}(k) = u_{\text{int}}(k - 1)$$

end


Example 6

- Introduce Anti-Windup and run again!




Conclusion 6

- With integrator "Anti Windup", the result is stable.
- Note that the torque settles at the load torque, 5 Nm.
- BUT, how do we set the control parameters?



Speed Control

With PI speed controller and 1'st order torque source




$$\frac{\omega(s)}{\omega^*(s)} = \frac{K_{\omega} (1 + s \cdot T_i)}{s^3 \cdot J \cdot T_i \cdot T_{tc} + s^2 \cdot J \cdot T_i + s \cdot K_{\omega} \cdot T_i + K_{\omega}}$$

3'rd order, how do we solve for the roots??

Symmetric optimum:1

Open loop transfer function

$$G(s) = K_{\omega} \frac{1 + s \cdot T_i}{s \cdot T_i} \cdot \frac{1}{1 + s \cdot T_{tc}} \cdot \frac{1}{s \cdot J}$$



Select k_{ω} to maximize phase margin

Symmetric optimum:2

$$\omega_0 = \frac{1}{\sqrt{T_i \cdot T_{tc}}} \quad T_i = a^2 \cdot T_{tc}, \text{ where } a > 1$$

$$\omega_0 = \frac{1}{\sqrt{T_i \cdot T_{tc}}} = \frac{1}{a \cdot T_{tc}} = \frac{a}{T_i}$$

$$|G(j\omega_0)| = \left| K_\omega \frac{1 + j \cdot a}{j \cdot a} \cdot \frac{1}{1 + \frac{j}{a}} \cdot \frac{1}{\frac{j \cdot a}{T_i} \cdot J} \right| = K_\omega \cdot \frac{T_i}{a \cdot J} = 1$$

$$K_\omega = \frac{a \cdot J}{T_i} = \frac{J}{a \cdot T_{tc}}$$

Symmetric optimum:3

Close loop characteristic equation: $s^3 \cdot J \cdot \frac{T_i^2}{a^2} + s^2 \cdot T_i + s \cdot a_i + \frac{a}{T_i} = 0$

One root: $s = -\omega_0 = -\frac{a}{T_i}$

Polynomial division gives: $s^2 \cdot \frac{T_i^2}{a^2} + s \cdot T_i \cdot \frac{a-1}{a} + 1 = 0$


Other roots: $s_{2,3} = -\omega_0 \left(\xi \pm \sqrt{\xi^2 - 1} \right) \quad \zeta = \frac{a-1}{2}$

Example $z = 1$, i.e. no complex poles:

$$\begin{aligned} a &= 3 \\ T_i &= 9 \cdot T_{tc} \\ K_w &= \frac{J}{3 \cdot T_{tc}} \end{aligned}$$

Conclusion 7

- With the right control parameters, the result is again stable, with no stationary errors



Example 7

- Try out oscillatory roots

$$s_{2,3} = -\omega_0 \left(\xi \pm \sqrt{\xi^2 - 1} \right)$$

$$\xi = \frac{a - 1}{2}$$

$$a = 2$$

$$T_i = 4 \cdot T_{tc}$$

$$K_w = \frac{J}{2 \cdot T_{tc}}$$

$$\xi = \frac{2 - 1}{2} = 0.5$$

Noisy speed signal...

A filter on the speed signal gives a 4'th order system.

- How to design??

The engineering solution:

1. Note, it's not the speed, but the filtered speed that is controlled !
2. The filter time constant is usually much longer than T_{tc} !
3. Replace the fast torque dynamics with the slow filter dynamics and design as with symmetric optimum on a 3'rd order system.


Example 8

- Filtered speed signal, $T_f = 50$ ms
– *Non-adjusted parameters*
- Adjust parameters:

$$a = 3$$

$$T_i = 9 \cdot T_f$$

$$K_w = \frac{J}{3 \cdot T_f}$$



That's all folks...

